



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Composite Materials, PhD



Week 3

Macromechanical Analysis of a Lamina

Part 2: 2D Stiffness and Compliance Matrix for Unidirectional Lamina

Saad R. Ahmed, Ph.D.

Mechanical Engineering Department

saadramadhan82@tu.edu.iq

Introduction

- • Overview of Macromechanical Analysis of a Lamina
- • Importance of Compliance and Stiffness Matrices
- • Applications in Composite Materials



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Topics to be Covered

- • Compliance and Stiffness Matrix
- • Transformation of Stresses and Strains
- • Engineering Constants
- • Strength Failure Theories
- • Example Calculations



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Objectives

- • Understand 2D Stiffness and Compliance Matrices
- • Apply Hooke's Law for 2D Angle Lamina
- • Analyze Global and Local Stress-Strain Relationships
- • Evaluate Strength Failure Theories

Compliance and Stiffness Matrix Elements in Terms of Elastic Constants



طريقته إلى النجاح
YOUR WAY TO SUCCESS




FIGURE 3.1

Application of stresses to find engineering constants of a unidirectional lamina




طريقك إلى النجاح
YOUR WAY TO SUCCESS

Pure Axial Load in Direction 1

Apply a pure axial load in direction 1

$$\sigma_1 \neq 0, \sigma_2 = 0, \tau_{12} = 0$$



$$\begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \gamma_{12} \end{bmatrix} = \begin{bmatrix} S_{11} & S_{12} & 0 \\ S_{12} & S_{22} & 0 \\ 0 & 0 & S_{66} \end{bmatrix} \begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \tau_{12} \end{bmatrix}$$

$$\varepsilon_1 = S_{11} \sigma_1$$

$$\varepsilon_2 = S_{12} \sigma_1$$

$$\gamma_{12} = 0$$

$$E_1 \equiv \frac{\sigma_1}{\varepsilon_1} = \frac{1}{S_{11}}$$

$$\longrightarrow S_{11} = \frac{1}{E_1}$$


$$\nu_{12} \equiv -\frac{\varepsilon_2}{\varepsilon_1} = -\frac{S_{12}}{S_{11}}$$

$$\longrightarrow S_{12} = -\frac{\nu_{12}}{E_1}$$

Pure Axial Load in Direction 2

Apply a pure axial load in direction 2

$$\sigma_1 = 0, \sigma_2 \neq 0, \tau_{12} = 0$$



$$\begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \gamma_{12} \end{bmatrix} = \begin{bmatrix} S_{11} & S_{12} & 0 \\ S_{12} & S_{22} & 0 \\ 0 & 0 & S_{66} \end{bmatrix} \begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \tau_{12} \end{bmatrix}$$



$$\varepsilon_1 = S_{12} \sigma_2$$

$$\varepsilon_2 = S_{22} \sigma_2$$

$$\gamma_{12} = 0$$

$$E_2 \equiv \frac{\sigma_2}{\varepsilon_2} = \frac{1}{S_{22}} \longrightarrow S_{22} = \frac{1}{E_2}$$

$$v_{21} \equiv -\frac{\varepsilon_1}{\varepsilon_2} = -\frac{S_{12}}{S_{22}} \longrightarrow S_{12} = -\frac{v_{21}}{E_2}$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Reciprocal Relationship

$$S_{12} = -\frac{v_{12}}{E_1}$$


$$S_{12} = -\frac{v_{21}}{E_2}$$

$$\frac{v_{12}}{E_1} = \frac{v_{21}}{E_2}$$

Pure Shear Load in Plane 12

Apply a pure shear load in Plane 12

$$\sigma_1 = 0, \sigma_2 = 0, \tau_{12} \neq 0$$



$$\begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \gamma_{12} \end{bmatrix} = \begin{bmatrix} S_{11} & S_{12} & 0 \\ S_{12} & S_{22} & 0 \\ 0 & 0 & S_{66} \end{bmatrix} \begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \tau_{12} \end{bmatrix} \longrightarrow \begin{aligned} \varepsilon_1 &= 0 \\ \varepsilon_2 &= 0 \\ \gamma_{12} &= S_{66} \tau_{12} \end{aligned}$$

$$G_{12} \equiv \frac{\tau_{12}}{\gamma_{12}} = \frac{1}{S_{66}} \longrightarrow S_{66} = \frac{1}{G_{12}}$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Compliance Matrix

$$\begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \gamma_{12} \end{bmatrix} = \begin{bmatrix} S_{11} & S_{12} & 0 \\ S_{12} & S_{22} & 0 \\ 0 & 0 & S_{66} \end{bmatrix} \begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \tau_{12} \end{bmatrix}$$

$$\begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \gamma_{12} \end{bmatrix} = \begin{bmatrix} \frac{1}{E_1} & -\frac{\nu_{12}}{E_1} & 0 \\ -\frac{\nu_{12}}{E_1} & \frac{1}{E_2} & 0 \\ 0 & 0 & \frac{1}{G_{12}} \end{bmatrix} \begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \tau_{12} \end{bmatrix}$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Coefficients of Stiffness Matrix

$$\begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \tau_{12} \end{bmatrix} = \begin{bmatrix} Q_{11} & Q_{12} & 0 \\ Q_{12} & Q_{22} & 0 \\ 0 & 0 & Q_{66} \end{bmatrix} \begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \gamma_{12} \end{bmatrix}$$



$$Q_{11} = \frac{S_{22}}{S_{11}S_{22} - S_{12}^2}$$

$$Q_{12} = - \frac{S_{12}}{S_{11}S_{22} - S_{12}^2}$$

$$Q_{22} = \frac{S_{11}}{S_{11}S_{22} - S_{12}^2}$$



$$\begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \tau_{12} \end{bmatrix} = \begin{bmatrix} \frac{E_1}{1 - \nu_{21}\nu_{12}} & \frac{\nu_{12} E_2}{1 - \nu_{21}\nu_{12}} & 0 \\ \frac{\nu_{12} E_2}{1 - \nu_{21}\nu_{12}} & \frac{E_2}{1 - \nu_{21}\nu_{12}} & 0 \\ 0 & 0 & G_{12} \end{bmatrix} \begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \gamma_{12} \end{bmatrix}$$

3D and 2D compliance matrices

$$\begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \varepsilon_3 \\ \gamma_{23} \\ \gamma_{31} \\ \gamma_{12} \end{bmatrix} = \begin{bmatrix} \frac{1}{E_1} & -\frac{\nu_{12}}{E_1} & -\frac{\nu_{13}}{E_1} & 0 & 0 & 0 \\ -\frac{\nu_{21}}{E_2} & \frac{1}{E_2} & -\frac{\nu_{23}}{E_2} & 0 & 0 & 0 \\ -\frac{\nu_{31}}{E_3} & -\frac{\nu_{32}}{E_3} & \frac{1}{E_3} & 0 & 0 & 0 \\ 0 & 0 & 0 & \frac{1}{G_{23}} & 0 & 0 \\ 0 & 0 & 0 & 0 & \frac{1}{G_{31}} & 0 \\ 0 & 0 & 0 & 0 & 0 & \frac{1}{G_{12}} \end{bmatrix} \begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \sigma_3 \\ \tau_{23} \\ \tau_{31} \\ \tau_{12} \end{bmatrix} \longrightarrow \begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \gamma_{12} \end{bmatrix} = \begin{bmatrix} \frac{1}{E_1} & -\frac{\nu_{12}}{E_1} & 0 \\ -\frac{\nu_{12}}{E_1} & \frac{1}{E_2} & 0 \\ 0 & 0 & \frac{1}{G_{12}} \end{bmatrix} \begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \tau_{12} \end{bmatrix}$$




طريقته إلى النجاح
YOUR WAY TO SUCCESS

3D and 2D stiffness matrices

$$\begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \sigma_3 \\ \tau_{23} \\ \tau_{31} \\ \tau_{12} \end{bmatrix} = \begin{bmatrix} \frac{1-\nu_{23}\nu_{32}}{E_2 E_3 \Delta} & \frac{\nu_{21} + \nu_{23}\nu_{31}}{E_2 E_3 \Delta} & \frac{\nu_{31} + \nu_{21}\nu_{32}}{E_2 E_3 \Delta} & 0 & 0 & 0 \\ \frac{\nu_{21} + \nu_{23}\nu_{31}}{E_2 E_3 \Delta} & \frac{1-\nu_{13}\nu_{31}}{E_1 E_3 \Delta} & \frac{\nu_{32} + \nu_{12}\nu_{31}}{E_1 E_3 \Delta} & 0 & 0 & 0 \\ \frac{\nu_{31} + \nu_{21}\nu_{32}}{E_2 E_3 \Delta} & \frac{\nu_{32} + \nu_{12}\nu_{31}}{E_1 E_3 \Delta} & \frac{1-\nu_{12}\nu_{21}}{E_1 E_2 \Delta} & 0 & 0 & 0 \\ 0 & 0 & 0 & G_{23} & 0 & 0 \\ 0 & 0 & 0 & 0 & G_{31} & 0 \\ 0 & 0 & 0 & 0 & 0 & G_{12} \end{bmatrix} \begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \varepsilon_3 \\ \gamma_{23} \\ \gamma_{31} \\ \gamma_{12} \end{bmatrix} \longrightarrow \begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \tau_{12} \end{bmatrix} = \begin{bmatrix} \frac{E_1}{1-\nu_{21}\nu_{12}} & \frac{\nu_{12} E_2}{1-\nu_{21}\nu_{12}} & 0 \\ \frac{\nu_{12} E_2}{1-\nu_{21}\nu_{12}} & \frac{E_2}{1-\nu_{21}\nu_{12}} & 0 \\ 0 & 0 & G_{12} \end{bmatrix} \begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \gamma_{12} \end{bmatrix}$$

Hooke's Law for a 2D Angle Lamina





طريقك إلى النجاح
YOUR WAY TO SUCCESS

Relationship of Global and Local Stresses

$$\begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \tau_{12} \end{bmatrix} = \begin{bmatrix} c^2 & s^2 & 2sc \\ s^2 & c^2 & -2sc \\ -sc & sc & c^2 - s^2 \end{bmatrix} \begin{bmatrix} \sigma_x \\ \sigma_y \\ \tau_{xy} \end{bmatrix}$$

$$\begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \tau_{12} \end{bmatrix} = [T] \begin{bmatrix} \sigma_x \\ \sigma_y \\ \tau_{xy} \end{bmatrix}$$



$$\begin{bmatrix} \sigma_x \\ \sigma_y \\ \tau_{xy} \end{bmatrix} = \begin{bmatrix} c^2 & s^2 & -2sc \\ s^2 & c^2 & 2sc \\ sc & -sc & c^2 - s^2 \end{bmatrix} \begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \tau_{12} \end{bmatrix}$$

$$\begin{bmatrix} \sigma_x \\ \sigma_y \\ \tau_{xy} \end{bmatrix} = [T]^{-1} \begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \tau_{12} \end{bmatrix}$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Relationship of Global and Local Strains

$$\begin{bmatrix} \epsilon_1 \\ \epsilon_2 \\ \gamma_{12} \end{bmatrix} = \begin{bmatrix} c^2 & s^2 & sc \\ s^2 & c^2 & -sc \\ -2sc & 2sc & c^2 - s^2 \end{bmatrix} \begin{bmatrix} \epsilon_x \\ \epsilon_y \\ \gamma_{xy} \end{bmatrix}$$

$$\begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \tau_{12} \end{bmatrix} = \begin{bmatrix} c^2 & s^2 & 2sc \\ s^2 & c^2 & -2sc \\ -sc & sc & c^2 - s^2 \end{bmatrix} \begin{bmatrix} \sigma_x \\ \sigma_y \\ \tau_{xy} \end{bmatrix}$$

$$\begin{bmatrix} \epsilon_1 \\ \epsilon_2 \\ \gamma_{12}/2 \end{bmatrix} = \begin{bmatrix} c^2 & s^2 & 2sc \\ s^2 & c^2 & -2sc \\ -sc & sc & c^2 - s^2 \end{bmatrix} \begin{bmatrix} \epsilon_x \\ \epsilon_y \\ \gamma_{xy}/2 \end{bmatrix}$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Relationship of Global and Local Strains

$$\begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \gamma_{12}/2 \end{bmatrix} = \begin{bmatrix} c^2 & s^2 & 2sc \\ s^2 & c^2 & -2sc \\ -sc & sc & c^2 - s^2 \end{bmatrix} \begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy}/2 \end{bmatrix}$$

$$\begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \gamma_{12}/2 \end{bmatrix} = [T] \begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy}/2 \end{bmatrix}$$



$$\begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy}/2 \end{bmatrix} = \begin{bmatrix} c^2 & s^2 & -2sc \\ s^2 & c^2 & 2sc \\ sc & -sc & c^2 - s^2 \end{bmatrix} \begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \gamma_{12}/2 \end{bmatrix}$$

$$\begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy}/2 \end{bmatrix} = [T]^{-1} \begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \gamma_{12}/2 \end{bmatrix}$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Expanding Global Strain-Local Strain Relationship

$$\begin{bmatrix} 1 & 0 & 0 \\ 0 & 1 & 0 \\ 0 & 0 & 1/2 \end{bmatrix} \begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy} \end{bmatrix} = [T]^{-1} \begin{bmatrix} 1 & 0 & 0 \\ 0 & 1 & 0 \\ 0 & 0 & 1/2 \end{bmatrix} \begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \gamma_{12} \end{bmatrix}$$

$$\begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy} \end{bmatrix} = \begin{bmatrix} 1 & 0 & 0 \\ 0 & 1 & 0 \\ 0 & 0 & 2 \end{bmatrix} [T]^{-1} \begin{bmatrix} 1 & 0 & 0 \\ 0 & 1 & 0 \\ 0 & 0 & 1/2 \end{bmatrix} \begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \gamma_{12} \end{bmatrix}$$

$$\begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy} \end{bmatrix} = [R][T]^{-1}[R]^{-1} \begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \gamma_{12} \end{bmatrix}$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Global Stress and Strain

$$\begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy} \end{bmatrix} = [R][T]^{-1}[R]^{-1} \begin{bmatrix} \varepsilon_1 \\ \varepsilon_2 \\ \gamma_{12} \end{bmatrix} \quad \longrightarrow \quad \begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy} \end{bmatrix} = [R][T]^{-1}[R]^{-1}[S] \begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \tau_{12} \end{bmatrix}$$

$$\begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy} \end{bmatrix} = [R][T]^{-1}[R]^{-1}[S][T] \begin{bmatrix} \sigma_x \\ \sigma_y \\ \tau_{xy} \end{bmatrix} \quad \longrightarrow \quad \begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy} \end{bmatrix} = \begin{bmatrix} \bar{S}_{11} & \bar{S}_{12} & \bar{S}_{16} \\ \bar{S}_{12} & \bar{S}_{22} & \bar{S}_{26} \\ \bar{S}_{16} & \bar{S}_{26} & \bar{S}_{66} \end{bmatrix} \begin{bmatrix} \sigma_x \\ \sigma_y \\ \tau_{xy} \end{bmatrix}$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Transformed Compliance Matrix

$$\begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy} \end{bmatrix} = \begin{bmatrix} \bar{S}_{11} & \bar{S}_{12} & \bar{S}_{16} \\ \bar{S}_{12} & \bar{S}_{22} & \bar{S}_{26} \\ \bar{S}_{16} & \bar{S}_{26} & \bar{S}_{66} \end{bmatrix} \begin{bmatrix} \sigma_x \\ \sigma_y \\ \tau_{xy} \end{bmatrix}$$

$$\bar{S}_{11} = S_{11}c^4 + (2S_{12} + S_{66})s^2c^2 + S_{22}s^4,$$

$$\bar{S}_{12} = S_{12}(s^4 + c^4) + (S_{11} + S_{22} - S_{66})s^2c^2,$$

$$\bar{S}_{22} = S_{11}s^4 + (2S_{12} + S_{66})s^2c^2 + S_{22}c^4,$$

$$\bar{S}_{16} = (2S_{11} - 2S_{12} - S_{66})sc^3 - (2S_{22} - 2S_{12} - S_{66})s^3c,$$

$$\bar{S}_{26} = (2S_{11} - 2S_{12} - S_{66})s^3c - (2S_{22} - 2S_{12} - S_{66})sc^3,$$

$$\bar{S}_{66} = 2(2S_{11} + 2S_{22} - 4S_{12} - S_{66})s^2c^2 + S_{66}(s^4 + c^4)$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Transformed Reduced Stiffness Matrix

$$\begin{bmatrix} \sigma_x \\ \sigma_y \\ \tau_{xy} \end{bmatrix} = \begin{bmatrix} \bar{Q}_{11} & \bar{Q}_{12} & \bar{Q}_{16} \\ \bar{Q}_{12} & \bar{Q}_{22} & \bar{Q}_{26} \\ \bar{Q}_{16} & \bar{Q}_{26} & \bar{Q}_{66} \end{bmatrix} \begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy} \end{bmatrix}$$

$$\bar{Q}_{11} = Q_{11}c^4 + Q_{22}s^4 + 2(Q_{12} + 2Q_{66})s^2c^2,$$

$$\bar{Q}_{12} = (Q_{11} + Q_{22} - 4Q_{66})s^2c^2 + Q_{12}(c^4 + s^4),$$


$$\bar{Q}_{16} = (Q_{11} - Q_{12} - 2Q_{66})c^3s - (Q_{22} - Q_{12} - 2Q_{66})s^3c,$$

$$\bar{Q}_{22} = Q_{11}s^4 + Q_{22}c^4 + 2(Q_{12} + 2Q_{66})s^2c^2,$$


$$\bar{Q}_{26} = (Q_{11} - Q_{12} - 2Q_{66})cs^3 - (Q_{22} - Q_{12} - 2Q_{66})c^3s,$$

$$\bar{Q}_{66} = (Q_{11} + Q_{22} - 2Q_{12} - 2Q_{66})s^2c^2 + Q_{66}(s^4 + c^4)$$

Transformation of stresses



Stresses in given coordinate system



Principal stresses



$$\sigma_1 = \sigma_x \cos^2 \theta + \sigma_y \sin^2 \theta + 2 \tau_{xy} \sin(\theta) \cos(\theta)$$

$$\tau_{12} = \sigma_x \sin(\theta) \cos(\theta) - \sigma_y \sin(\theta) \cos(\theta) + \tau_{xy} (\cos^2 \theta - \sin^2 \theta)$$






طريقك إلى النجاح
YOUR WAY TO SUCCESS



Stress Transformation



Stresses in given coordinate system



Principal stresses





طريقك إلى النجاح
YOUR WAY TO SUCCESS

Example 3.1 Structural Design Challenge

You are an engineer designing a lightweight aerospace panel. The material used is a unidirectional composite lamina subjected to normal and shear stresses.

- How does stress transformation affect material behavior?
- How would a 45° rotation impact the stress distribution?

Given Data:

A unidirectional composite lamina is subjected to the following stresses:

- Normal stress in the x-direction: $\sigma_x = 50$ MPa
- Normal stress in the y-direction: $\sigma_y = 30$ MPa
- Shear stress: $\tau_{xy} = 10$ MPa
- The lamina is rotated by 45° .

We need to find the transformed stresses ($\sigma'_{x'}$, $\sigma'_{y'}$, and $\tau'_{x'y'}$) in the new coordinate system.

Solution:

$$\sigma'_x = \frac{\sigma_x + \sigma_y}{2} + \frac{\sigma_x - \sigma_y}{2} \cos 2\theta + \tau_{xy} \sin 2\theta$$

$$\sigma'_y = \frac{\sigma_x + \sigma_y}{2} - \frac{\sigma_x - \sigma_y}{2} \cos 2\theta - \tau_{xy} \sin 2\theta$$

$$\tau'_{xy} = -\frac{\sigma_x - \sigma_y}{2} \sin 2\theta + \tau_{xy} \cos 2\theta$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS



طريقك إلى النجاح
YOUR WAY TO SUCCESS

For $\theta = 45^\circ$:

- $\cos 90^\circ = 0$
- $\sin 90^\circ = 1$

Using the given values ($\sigma_x = 50$, $\sigma_y = 30$, $\tau_{xy} = 10$):

$$\sigma'_x = \frac{50 + 30}{2} + \frac{50 - 30}{2} \cdot 0 + (10 \times 1)$$

$$\sigma'_x = \frac{80}{2} + 0 + 10 = 40 + 10 = 50 \text{ MPa}$$

$$\sigma'_y = \frac{50 + 30}{2} - \frac{50 - 30}{2} \cdot 0 - (10 \times 1)$$

$$\sigma'_y = \frac{80}{2} - 0 - 10 = 40 - 10 = 30 \text{ MPa}$$

$$\tau'_{xy} = -\frac{50 - 30}{2} \cdot 1 + (10 \times 0)$$

$$\tau'_{xy} = -\frac{20}{2} + 0 = -10 \text{ MPa}$$

Example 3.2



طريقك إلى النجاح
YOUR WAY TO SUCCESS

You are analyzing the structural integrity of a Graphite/Epoxy lamina under multi-axial loading conditions.

How can we determine if a lamina will fail under given stresses?

Which failure theories should be used?



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Using Maximum Stress Failure Theory:

- Failure occurs if any of these conditions are violated:

$$\sigma_1 < X_t, \quad \sigma_1 > X_c$$

$$\sigma_2 < Y_t, \quad \sigma_2 > Y_c$$

$$\tau_{12} < S$$

Evaluating each condition:


- $100 < 200 \rightarrow$ Safe
- $30 < 50 \rightarrow$ Safe
- $20 < 40 \rightarrow$ Safe

Result:

- The lamina is safe under the given stress conditions.

Pure Axial Load in Direction x

$$\sigma_x \neq 0, \sigma_y = 0, \tau_{xy} = 0$$



$$\begin{bmatrix} \epsilon_x \\ \epsilon_y \\ \gamma_{xy} \end{bmatrix} = \begin{bmatrix} \bar{S}_{11} & \bar{S}_{12} & \bar{S}_{16} \\ \bar{S}_{12} & \bar{S}_{22} & \bar{S}_{26} \\ \bar{S}_{16} & \bar{S}_{26} & \bar{S}_{66} \end{bmatrix} \begin{bmatrix} \sigma_x \\ \sigma_y \\ \tau_{xy} \end{bmatrix}$$

FIGURE 3.3

Application of stresses to find engineering constants of an angle lamina



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Engineering Constants

$$\varepsilon_x = \bar{S}_{11} \sigma_x$$


$$\varepsilon_y = \bar{S}_{12} \sigma_x$$

$$\gamma_{xy} = \bar{S}_{16} \sigma_x$$

$$E_x \equiv \frac{\sigma_x}{\varepsilon_x} = \frac{1}{\bar{S}_{11}}$$


$$\nu_{xy} \equiv -\frac{\varepsilon_y}{\varepsilon_x} = -\frac{\bar{S}_{12}}{\bar{S}_{11}}$$

$$\frac{1}{m_x} \equiv -\frac{\sigma_x}{\gamma_{xy} E_1} = -\frac{1}{\bar{S}_{16} E_1}$$



Pure Axial Load in Direction y

$$\sigma_x = 0, \sigma_y \neq 0, \tau_{xy} = 0$$



$$\begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy} \end{bmatrix} = \begin{bmatrix} \bar{S}_{11} & \bar{S}_{12} & \bar{S}_{16} \\ \bar{S}_{12} & \bar{S}_{22} & \bar{S}_{26} \\ \bar{S}_{16} & \bar{S}_{26} & \bar{S}_{66} \end{bmatrix} \begin{bmatrix} \sigma_x \\ \sigma_y \\ \tau_{xy} \end{bmatrix}$$

FIGURE 3.4

Application of stresses to find engineering constants of an angle lamina



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Engineering Constants

$$\varepsilon_x = \bar{S}_{12} \sigma_y$$

$$\varepsilon_y = \bar{S}_{22} \sigma_y$$


$$\gamma_{xy} = \bar{S}_{26} \sigma_y$$

$$\nu_{yx} \equiv -\frac{\varepsilon_x}{\varepsilon_y} = -\frac{\bar{S}_{12}}{\bar{S}_{22}}$$

$$E_y \equiv \frac{\sigma_y}{\varepsilon_y} = \frac{1}{\bar{S}_{22}}$$


$$\frac{1}{m_y} \equiv -\frac{\sigma_y}{\gamma_{xy} E_1} = -\frac{1}{\bar{S}_{26} E_1}$$

$$\frac{\nu_{yx}}{E_y} = \frac{\nu_{xy}}{E_x}$$



Pure Shear Load in x-y Plane

$$\sigma_x = 0, \sigma_y = 0, \tau_{xy} \neq 0$$



$$\begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy} \end{bmatrix} = \begin{bmatrix} \bar{S}_{11} & \bar{S}_{12} & \bar{S}_{16} \\ \bar{S}_{12} & \bar{S}_{22} & \bar{S}_{26} \\ \bar{S}_{16} & \bar{S}_{26} & \bar{S}_{66} \end{bmatrix} \begin{bmatrix} \sigma_x \\ \sigma_y \\ \tau_{xy} \end{bmatrix}$$

FIGURE 3.5

Application of stresses to find engineering constants of an angle lamina



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Engineering Constants

$$\varepsilon_x = \bar{S}_{16} \tau_{xy}$$


$$\varepsilon_y = \bar{S}_{26} \tau_{xy}$$

$$\gamma_{xy} = \bar{S}_{66} \tau_{xy}$$

$$\frac{1}{m_x} = -\frac{\tau_{xy}}{\varepsilon_x E_1} = -\frac{1}{\bar{S}_{16} E_1}$$

$$\frac{1}{m_y} = -\frac{\tau_{xy}}{\varepsilon_y E_1} = -\frac{1}{\bar{S}_{26} E_1}$$

$$G_{xy} \equiv \frac{\tau_{xy}}{\gamma_{xy}} = \frac{1}{\bar{S}_{66}}$$





طريقته إلى النجاح
YOUR WAY TO SUCCESS

Stress-Strain Relationships for Angle Lamina

$$\begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy} \end{bmatrix} = \begin{bmatrix} \bar{S}_{11} & \bar{S}_{12} & \bar{S}_{16} \\ \bar{S}_{12} & \bar{S}_{22} & \bar{S}_{26} \\ \bar{S}_{16} & \bar{S}_{26} & \bar{S}_{66} \end{bmatrix} \begin{bmatrix} \sigma_x \\ \sigma_y \\ \tau_{xy} \end{bmatrix}$$

$$\begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy} \end{bmatrix} = \begin{bmatrix} \frac{1}{E_x} & -\frac{\nu_{xy}}{E_x} & -\frac{m_x}{E_1} \\ -\frac{\nu_{xy}}{E_x} & \frac{1}{E_y} & -\frac{m_y}{E_1} \\ -\frac{m_x}{E_1} & -\frac{m_y}{E_1} & \frac{1}{G_{xy}} \end{bmatrix} \begin{bmatrix} \sigma_x \\ \sigma_y \\ \tau_{xy} \end{bmatrix}$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Engineering Constant E_x of an Angle Lamina

$$\frac{1}{E_x} = \bar{S}_{11}$$

$$= S_{11}c^4 + (2S_{12} + S_{66})s^2c^2 + S_{22}s^4$$

$$= \frac{1}{E_1}c^4 + \left(\frac{1}{G_{12}} - \frac{2\nu_{12}}{E_1} \right) s^2c^2 + \frac{1}{E_2}s^4$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Engineering Constant E_y of an Angle Lamina

$$\frac{1}{E_y} = \bar{S}_{22}$$

$$= S_{11}s^4 + (2S_{12} + S_{66})c^2s^2 + S_{22}c^4$$

$$= \frac{1}{E_1}s^4 + \left(-\frac{2\nu_{12}}{E_1} + \frac{1}{G_{12}} \right) c^2s^2 + \frac{1}{E_2}c^4$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Engineering Constant G_{xy} of an Angle Lamina

$$\frac{1}{G_{xy}} = \bar{S}_{66}$$

$$= 2(2S_{11} + 2S_{22} - 4S_{12} - S_{66})s^2c^2 + S_{66}(s^4 + c^4)$$

$$= 2\left(\frac{2}{E_1} + \frac{2}{E_2} + \frac{4\nu_{12}}{E_1} - \frac{1}{G_{12}}\right)s^2c^2 + \frac{1}{G_{12}}(s^4 + c^4)$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Engineering Constant m_x of an Angle Lamina

$$m_x = -\bar{S}_{16} E_1$$

$$= -E_1 \left[(2S_{11} - 2S_{12} - S_{66})sc^3 - (2S_{22} - 2S_{12} - S_{66})s^3c \right]$$

$$= E_1 \left[\left(-\frac{2}{E_1} - \frac{2\nu_{12}}{E_1} + \frac{1}{G_{12}} \right) sc^3 + \left(\frac{2}{E_2} + \frac{2\nu_{12}}{E_1} - \frac{1}{G_{12}} \right) s^3c \right]$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Engineering Constant m_y of an Angle Lamina

$$m_y = -\bar{S}_{26} E_1$$

$$= -E_1 \left[(2S_{11} - 2S_{12} - S_{66})s^3c - (2S_{22} - 2S_{12} - S_{66})sc^3 \right]$$

$$= E_1 \left[\left(-\frac{2}{E_1} - \frac{2\nu_{12}}{E_1} + \frac{1}{G_{12}} \right) s^3c + \left(\frac{2}{E_2} + \frac{2\nu_{12}}{E_1} - \frac{1}{G_{12}} \right) sc^3 \right]$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Example 3.3 Optimizing Engineering Constants

You are tasked with selecting a composite lamina for an automotive application requiring high stiffness and minimal weight.

- What role do engineering constants play in material selection?
- How can compliance and stiffness matrices be used for material evaluation?

A composite lamina with the following properties:

- Longitudinal modulus: $E_1 = 140$ GPa
- Transverse modulus: $E_2 = 10$ GPa
- Shear modulus: $G_{12} = 5$ GPa
- Poisson's ratio: $\nu_{12} = 0.3$

Solution



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Using stress transformation equations:

$$\sigma'_x = \frac{\sigma_x + \sigma_y}{2} + \frac{\sigma_x - \sigma_y}{2} \cos 2\theta + \tau_{xy} \sin 2\theta$$

$$\sigma'_y = \frac{\sigma_x + \sigma_y}{2} - \frac{\sigma_x - \sigma_y}{2} \cos 2\theta - \tau_{xy} \sin 2\theta$$

$$\tau'_{xy} = -\frac{\sigma_x - \sigma_y}{2} \sin 2\theta + \tau_{xy} \cos 2\theta$$

Substituting values for $\theta = 45^\circ$:

- $\sigma'_x = 40$ MPa
- $\sigma'_y = 20$ MPa
- $\tau'_{xy} = 15$ MPa



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Invariant Form of Stiffness Matrix

$$\begin{bmatrix} \sigma_x \\ \sigma_y \\ \tau_{xy} \end{bmatrix} = \begin{bmatrix} \bar{Q}_{11} & \bar{Q}_{12} & \bar{Q}_{16} \\ \bar{Q}_{12} & \bar{Q}_{22} & \bar{Q}_{26} \\ \bar{Q}_{16} & \bar{Q}_{26} & \bar{Q}_{66} \end{bmatrix} \begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy} \end{bmatrix},$$

$$\bar{Q}_{11} = U_1 + U_2 \cos 2\theta + U_3 \cos 4\theta$$

$$\bar{Q}_{12} = U_4 - U_3 \cos 4\theta$$

$$\bar{Q}_{22} = U_1 - U_2 \cos 2\theta + U_3 \cos 4\theta$$

$$\bar{Q}_{16} = \frac{U_2}{2} \sin 2\theta + U_3 \sin 4\theta$$

$$\bar{Q}_{26} = \frac{U_2}{2} \sin 2\theta - U_3 \sin 4\theta$$

$$\bar{Q}_{66} = \frac{1}{2}(U_1 - U_4) - U_3 \cos 4\theta$$

$$U_1 = \frac{1}{8}(3Q_{11} + 3Q_{22} + 2Q_{12} + 4Q_{66})$$

$$U_2 = \frac{1}{2}(Q_{11} - Q_{22})$$

$$U_3 = \frac{1}{8}(Q_{11} + Q_{22} - 2Q_{12} - 4Q_{66})$$

$$U_4 = \frac{1}{8}(Q_{11} + Q_{22} + 6Q_{12} - 4Q_{66})$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Invariant Form of Compliance Matrix

$$\begin{bmatrix} \varepsilon_x \\ \varepsilon_y \\ \gamma_{xy} \end{bmatrix} = \begin{bmatrix} \bar{S}_{11} & \bar{S}_{12} & \bar{S}_{16} \\ \bar{S}_{12} & \bar{S}_{22} & \bar{S}_{26} \\ \bar{S}_{16} & \bar{S}_{26} & \bar{S}_{66} \end{bmatrix} \begin{bmatrix} \sigma_x \\ \sigma_y \\ \tau_{xy} \end{bmatrix},$$

$$\bar{S}_{11} = V_1 + V_2 \cos 2\theta + V_3 \cos 4\theta,$$

$$\bar{S}_{12} = V_4 - V_3 \cos 4\theta,$$

$$\bar{S}_{22} = V_1 - V_2 \cos 2\theta + V_3 \cos 4\theta,$$

$$\bar{S}_{16} = V_2 \sin 2\theta + 2V_3 \sin 4\theta,$$

$$\bar{S}_{26} = V_2 \sin 2\theta - 2V_3 \sin 4\theta,$$

$$\bar{S}_{66} = 2(V_1 - V_4) - 4V_3 \cos 4\theta,$$

$$V_1 = \frac{1}{8}(3S_{11} + 3S_{22} + 2S_{12} + S_{66}),$$

$$V_2 = \frac{1}{2}(S_{11} - S_{22}),$$

$$V_3 = \frac{1}{8}(S_{11} + S_{22} - 2S_{12} - S_{66}),$$

$$V_4 = \frac{1}{8}(S_{11} + S_{22} + 6S_{12} - S_{66})$$

كلية الهندسة - COLLEGE OF ENGINEERING

جامعة تكريت - Tikrit University

Strength Failure Theories for an Angle Lamina



طريقك إلى النجاح
YOUR WAY TO SUCCESS

- The failure theories are generally based on the normal and shear strengths of a unidirectional lamina.
- In the case of a unidirectional lamina, the five strength parameters are:
 - ❑ Longitudinal tensile strength $(\sigma_1^T)_{ult}$
 - ❑ Longitudinal compressive strength $(\sigma_1^C)_{ult}$
 - ❑ Transverse tensile strength $(\sigma_2^T)_{ult}$
 - ❑ Transverse compressive strength $(\sigma_2^C)_{ult}$
 - ❑ In-plane shear strength $(\tau_{12})_{ult}$

Maximum Stress Failure Theory


- The lamina is considered to be failed if:

$$-(\sigma_1^C)_{ult} \leq \sigma_1 \leq (\sigma_1^T)_{ult}, \text{ or}$$

$$-(\sigma_2^C)_{ult} \leq \sigma_2 \leq (\sigma_2^T)_{ult}, \text{ or}$$

$$-(\tau_{12})_{ult} \leq \tau_{12} \leq (\tau_{12})_{ult}$$

is violated.



- Note that all five strength parameters are positive numbers.
- Each component of stress does not interact with each other.

Example 3.4

Find the maximum value of $S > 0$ if a stress of $\sigma_x = 2S$, $\sigma_y = -3S$, and $\tau_{xy} = 4S$ is applied to a 60° lamina of Graphite/Epoxy. Use Maximum Stress failure theory. Use properties of a unidirectional Graphite/Epoxy lamina given in Table 2.1 of the textbook [Mechanics of Composite Materials by Autar Kaw](#).




FIGURE 3.5
Off-axis loading in the x-direction



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Solution

The stresses in the local axes are

$$\begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \tau_{12} \end{bmatrix} = \begin{bmatrix} 0.2500 & 0.7500 & 0.8660 \\ 0.7500 & 0.2500 & -0.8660 \\ -0.4330 & 0.4330 & -0.5000 \end{bmatrix} \begin{bmatrix} 2S \\ -3S \\ 4S \end{bmatrix}$$

$$= \begin{bmatrix} 0.1714 \times 10^1 \\ -0.2714 \times 10^1 \\ -0.4165 \times 10^1 \end{bmatrix} S.$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Solution

The ultimate strengths of a unidirectional Graphite/Epoxy lamina are:

$$\left(\sigma_1^T\right)_{ult} = 1500 \text{ MPa},$$

$$\left(\sigma_1^C\right)_{ult} = 1500 \text{ MPa},$$

$$\left(\sigma_2^T\right)_{ult} = 40 \text{ MPa},$$

$$\left(\sigma_2^C\right)_{ult} = 246 \text{ MPa},$$

$$\left(\tau_{12}\right)_{ult} = 68 \text{ MPa}.$$



طريقك إلى النجاح
YOUR WAY TO SUCCESS

Solution

Then using the inequalities of the Maximum Stress Failure Theory:

$$-1500(10^6) < 0.1714(10^1)S < 1500(10^6),$$

$$-246(10^6) < -0.2714(10^1)S < 40(10^6),$$

$$-68(10^6) < -0.4165(10^1)S < 68(10^6),$$

$$\text{or, } -875.1(10^6) < S < 875.1(10^6),$$

$$-14.73(10^6) < S < 90.64(10^6)$$

$$-16.33(10^6) < S < 16.33(10^6).$$

$$\begin{bmatrix} \sigma_1 \\ \sigma_2 \\ \tau_{12} \end{bmatrix} = \begin{bmatrix} 0.1714 \times 10^1 \\ -0.2714 \times 10^1 \\ -0.4165 \times 10^1 \end{bmatrix} S.$$

All the inequality conditions (and $S > 0$) are satisfied if $0 < S < 16.33 \text{ MPa}$.

The above inequalities also show that the angle lamina will fail in shear. The maximum stress that can be applied before failure is:

$$\sigma_x = 32.66 \text{ MPa}, \sigma_x = -48.99 \text{ MPa}, \tau_{xy} = 65.32 \text{ MPa}.$$